

Stage II Vapor Recovery regulations are mandated by section 182(b)(3)(A) of the Clean Air Act Amendments of 1990 (CAAA)

States with areas designated moderate, serious, severe or extreme for ozone nonattainment are required to implement a stage II vapor recovery program. States may require Stage II controls in areas other than where stage II is mandated federally.

Owners and operators of gasoline-dispensing facilities subject to Stage II regulations are responsible for the proper installation and maintenance of Stage II equipment...

IS YOUR STATION LOCATED IN A STAGE II AREA??

ANS Distributing has everything your station needs to be compliant! Order your hanging hardware and station equipment today!



STATE	STAGE II COUNTY REQUIREMENTS	For More Information on County Requirements:
Alabama	Stage II vapor recovery currently not required in Alabama with no plans of implementation	Contact: Alabama Dept. of Environmental Mgt. 334-271-7759
Alaska	Stage II vapor recovery currently not required in Alaska	Contact: Dept. of Environmental conservation 907-465-5206
Arizona	Stage II controls are required in the Phoenix metropolitan area which includes: Portions of Maricopa, Pinal and Yavapai	Contact: Department of Weights and Measures, 623-463-9941
Arkansas	Stage II vapor recovery currently not required in Arkansas	Contact: Arkansas dept. of Environmental Quality

Is Your Station Located in a Stage II vapor Recovery Area?

		214-665-7367
California	Stage II controls are required throughout the state of California. Stage II requirements are enforced by 35 local air pollution controls districts	Contact: Division of Water Quality 916-322-2496
Colorado	Stage II currently not required in Colorado, Denver area is classified as transitional for nonattainment of ozone	Contact: Department of Oil inspections 303-620-4300
Connecticut	Stage II currently required throughout the state of Connecticut. The state is designated as nonattainment for ozone, with all but the southwestern portion of the state classified as serious. Fairfield County, except Shelton but including New Milford and Bridgewater is classified as severe.	Contact: Bureau of Air Management Dep. 860-424-3028
Delaware	Stage II is required throughout the state. All tanks with annual gasoline throughputs greater than 10,000 gallons must have stage II vapor recovery	Contact: UST Branch 302-395-2500
Florida	Stage II required in Broward, Miami Dade and Palm Beach Counties. However facilities beginning operation after May 15, 2007 no longer require stage II	Contact: Martin Costello 850-921-9578
Georgia	Stage II required at all gasoline dispensing facilities in the following counties: Cherokee, Clayton, Cobb, Cowets, DeKalb, Douglas, Fayette, Forsyth, Fulton, Gwinnett, Henry, Paulding, and Rockdale	Contact: Underground storage tank management 404-363-7042
Hawaii	Stage II vapor recovery is not currently required in Hawaii	Contact: Clean Air Dep. 808-586-4200
Idaho	Stage II vapor recovery is not currently required in Idaho	Contact: DEQ 280-373-0502
Illinois	Stage II is currently required in the following counties: Cook, DuPage, Kane, Lake, McHenry, Will, and in the Oswego Township of Kendall County, the Auxsable, Goose Lake townships of Grundy County. All gasoline facilities in these areas that dispense for than 10,000 gallons or more of gasoline per month must comply with Stage II Vapor Recovery	Contact: Illinois environmental protection Agency 217-782-5811
Indiana	Stage II is currently required in the following counties: Clark, Floyd, Lake and Porter	Contact: Office of Land Quality 317-233-0432
Iowa	Stage II is not currently required in Iowa	Contact: Dept. of Natural Resources 515-281-8135
Kansas	Stage II is not currently required in Kansas , however stage I controls are required in Wyandotte, and Johnson counties	Contact: Bureau of Air & Radiation 785-296-1579
Kentucky	Stage II is required in the following Kentucky counties: Campbell, Jefferson, and Kenton	Contact: Petroleum Storage Tank Environmental Assurance office

Is Your Station Located in a Stage II vapor Recovery Area?

		502-564-5981
Louisiana	Stage II vapor recovery is required in the parishes of Ascension, East Baton Rouge, Iberville, Livingston, Point Coupee and West Baton Rouge	Contact: DEQ 225-219-3600
Maine	Stage II vapor recovery is required in York, Cumberland and Sagadahoc counties for all gasoline facilities with annual throughputs of more than 1 million gallons	Contact: Department of environmental protection 207-822-6355
Maryland	Stage II is required in Maryland's three ozone nonattainment areas, all of which are classified as severe. The Baltimore City and Anne Arundel, Baltimore, Carroll, Harford and Howard counties. The Philadelphia nonattainment area includes Cecil county The Washington nonattainment area includes Calvert, Charles, Frederick, Montgomery, and Prince George's Counties	Contact Maryland Dept. of Environment 410-537-3231
Massachusetts	Stage II is required throughout the state Stage II must be installed upon new construction or substantial modification of existing facilities	Contact: DEQ 617-556-1144
Michigan	Stage II vapor recovery requirements are not required in Michigan	Contact: DEQ 312-886-6043
Minnesota	Stage II vapor recovery requirements are not required in Minnesota	Contact: MPCA 651-297-2274
Mississippi	Stage II vapor recovery is not required in Mississippi	Contact: DEQ 404-562-9045
Missouri	Stage II vapor recovery is required in the following counties: Jefferson, Franklin, St. Charles, St. Louis and the city of St. Louis	Contact: stage II unit 314-416-2960
Montana	Stage II vapor recovery is not currently required within the state of Montana	Contact: DEQ 406-444-4323
Nebraska	Stage II vapor recovery is not currently required in the state of Nebraska	Contact: DEQ 402-471-9465
Nevada	Stage II vapor recovery is required in the Las Vegas and Reno areas. Clark County is waiting on CARB to finalize its phase II requirements before the county decides to adopt phase II	Contact: Division of Environmental protection 775-784-7200
New Hampshire	Stage II is required in Hillsborough, Rockingham, Merrimack, and Strafford counties with gasoline throughput of more than 420,000 gallons annually	Contact: Department of Environment Services 603-271-3644
New Jersey	Stage II vapor recovery is required throughout the state of New Jersey	Contact: Air Quality Permitting Program 609-633-2829
New Mexico	Stage II vapor recovery is not currently required in New Mexico	Contact: Petroleum storage tank bureau 214-665-7367
New York	Stage II vapor recovery is required in the following counties: Nassau, Suffolk, Rockland, and Westchester	Contact: Division of Air Resources 518-402-8452
North Carolina	Stage II Vapor recovery is not currently required in North Carolina	Contact: UST section 919-733-1484
North Dakota	Stage II Vapor Recovery is not currently required in North	Contact: state regulatory info

Is Your Station Located in a Stage II vapor Recovery Area?

	Dakota	701-328-5166
Ohio	Stage II is required in the following 16 Ohio counties: Ashtabula, Butler, Clark, Clermont, Cuyahoga, Geauga, Greene, Hamilton, Lake, Lorain, Medina, Miami, Montgomery, Portage, Summit and Warren	Contact: Division of Air Pollution Control 614-644-3593
Oklahoma	Stage II Vapor Recovery is not currently required in Oklahoma	Contact: DEQ 214-665-7367
Oregon	Stage II vapor recovery is currently required in Multnomah, Clackamas and Washington counties	Contact: DEQ 503-229-5473
Pennsylvania	Stage II vapor recovery is required in the Pittsburgh area-counties of Allegheny, Armstrong, Beaver, Butler, Fayette, Washington, and Westmoreland as well as several areas of Bucks, Chester, Delaware, Montgomery and Philadelphia	Contact: Division of Storage Tanks 717-772-3994
Rhode Island	Stage II vapor recovery is required throughout the state of Rhode Island, the entire state is classified as serious nonattainment for ozone	Contact: Rhode Island Office of Air Resources 401-222-2808 X 7029
South Carolina	Stage II vapor recovery is not currently required for South Carolina	Contact: Regulatory Compliance Division 803-898-4350
South Dakota	Stage II vapor recovery is not currently required for South Dakota	Contact: Air Quality 605-773-3151
Tennessee	Stage II vapor recovery is required for the following counties: Davidson, Rutherford, Shelby, Sumner, Williamson and Wilson	Contact: TDEC 615-532-6822
Texas	Stage II vapor recovery is required in the Dallas/ Fort Worth area: Collin, Dallas, Denton, and Tarrant counties, El Paso County, the Beaumont/Port Arthur area (Hardin, Jefferson, Orange counties) and the Houston/Galveston area (Brazoria, Chambers, Fort Bend, Galveston, Harris, Liberty, Montgomery, and Waller)	Contact: Austin central office 512-239-6832 Beaumont/Pt. Arthur area 409-898-3838 Dallas/Ft. Worth 817-588-5800 El Paso area 915-834-4949 Houston/Galveston 713-767-3600
Utah	Stage II vapor recovery is currently not required in Utah	Contact: Division of Air Quality 801-536-4000
Vermont	Stage II required statewide at gasoline pumps dispensing at least 400,000 gallons annually	Contact: Air Pollution Control Division 802-241-3840
Virginia	Stage II Vapor Recovery controls are currently required in Charles City, Chesterfield, Hanover, Henrico, Arlington, Fairfax, Loudoun, Prince Williams and Stafford counties, also in the cities of Colonial Heights, Hopewell, Richmond, Alexandria, Fairfax, Falls Church, Manassas and Manassas Park	Contact: DEQ 703-583-3913
Washington	Stage II is required for facilities with annual throughputs of	Contact: Compliance &

Is Your Station Located in a Stage II vapor Recovery Area?

	more than 600,000 gallons of gasoline in Clark, King, Pierce, and Snohomish counties, and in Kitsap county which has a maintenance plan	Enforcement Air Quality Program Ecology 360-407-6856
West Virginia	Stage II vapor recovery is currently not required in West Virginia	Contact: Division of Air Quality 304-926-0475
Wisconsin	Stage II vapor recovery is required in the following counties: Kenosha, Kewaunee, Manitowoc, Milwaukee, Ozaukee, Racine, Sheboygan, Washington, and Waukesha which distribute more than 10,000 gallons of gasoline per month; stage II vapor recovery is required statewide for large petroleum retailers distributing more than 2 million gallons of gasoline per year	Contact: DNR 608-267-7540
Wyoming	Stage II vapor recovery is not currently required for Wyoming	Contact: U.S. EPA 303-312-6479

To purchase Stage II Vapor recovery equipment online now, click on the link below...

<http://www.ansdistributing.com/ans/vre/vavr>

To purchase conventional equipment online now, click on the link below...

<http://www.ansdistributing.com/ans/nvn>

To view the ANS Distributing website and to purchase all other petroleum handling equipment click on the link below...

<http://www.ansdistributing.com/>

For equipment questions, a quote, or to have a salesman contact you, email us!

marketing@ansdistributing.com